

REVIEW

Potential Hazardous Waste Site - Inspection Report

Site Name Amoco #1 Fred CO.  
Site Location Hackberry LA  
Site Number LAD981910656 Date of Survey 5-14-87  
Inspected by \_\_\_\_\_ State FIT ☒ TAT \_\_\_\_\_  
Other (specify) \_\_\_\_\_ SUPERFUND  
Received From McKee FILE  
Date rec'd by Water Supply Branch 6/16/87 JUL 17 1992  
Type samples: NONE REORGANIZED  
\_\_\_\_\_ on-site \_\_\_\_\_ on-site \_\_\_\_\_ on-site \_\_\_\_\_ on-site  
\_\_\_\_\_ SOIL \_\_\_\_\_ SURFACE WATER \_\_\_\_\_ GROUND WATER \_\_\_\_\_ DRINKING WATER  
\_\_\_\_\_ off-site \_\_\_\_\_ off-site \_\_\_\_\_ off-site \_\_\_\_\_ off-site  
Type contaminant(s): NA  
\_\_\_\_\_ ORGANICS \_\_\_\_\_ INORGANICS \_\_\_\_\_ RADIONUCLIDES \_\_\_\_\_ MICROBIOLOGICAL

Summary: THE SITE IS A PETROLEUM PRODUCTION FACILITY WITH 18 STORAGE TANKS, 7 SEPARATORS, AND 3 SURFACE IMPOUNDMENTS FOR ESTUARY DISCHARGE. SOME SURFACE WATER CONTAMINATION HAS POSSIBLY ACCURED, BECAUSE OF SALT WATER IS FREELY RELEASED TO THE SURFACE FROM THE OIL AND SALT WATER SEPARATION PROCESS. SURFACE WATER CONTAMINATION IS NOT A DRINKING WATER CONCERN BECAUSE SURFACE WATER IS NOT A DRINKING WATER SOURCE. GROUNDWATER IS THE DRINKING WATER SOURCE FOR HACKBERRY WHICH IS APPROXIMATELY ONE MILE FROM SITE. THE LOUISIANA DEPARTMENT OF NATURAL RESOURCES, OFFICE OF CONSERVATION MAKES PERIODIC INSPECTIONS OF THE FACILITY. BECAUSE THE DNR SEEMS TO HAVE ADEQUATE CONTROL ON THE SITE WE AGREE THAT NO FURTHER ACTION IS REQUIRED BY FIT.

NOTE: THE PRELIMINARY ASSESSMENT REPORT WAS RECEIVED IN OUR OFFICE ON 5-18-87, WHICH IS AFTER THE SITE INSPECTION SURVEY WAS CONDUCTED (5-14-87).

Concurrence:

D. M. ... 6/2/87

Jose H. Rodriguez 6-19-87  
Signature and Date